

Suspended Working Platform

Past Incident/ Accident:

柴灣致命工業意外 工人連吊船墮下死亡

2019年9月3日 17:31



【Now新聞台】柴灣一個地盤發生致命工業意外，一個工人隨工作吊船由高處墮下死亡。

現場是柴灣道近永泰道一個建築地盤，警員到場調查。

下午大約一時，一名工人乘吊船在外牆工作，期間懷疑吊船鋼纜鬆脫，工人連吊船由高處墮下，其他工人發現報警，消防員及救護員到場拯救，工人當場證實死亡，勞工處正調查意外原因。

強烈怪風吹襲 兩工人被困外牆吊船險象環生

環球財經 19:30 2020/07/31 0 讚好 0



紅磡商廈外牆出現驚險一幕！兩名工人在狂風吹襲下被困十多樓吊船，吊船晃動間擊破玻璃幕牆，兩人被碎片割傷，最終消防員到場將兩人救起送院。

事發於周四（30/7）下午四時許，兩名工人於紅磡海濱廣場1座外牆，乘搭吊船清潔玻璃幕牆，垂吊至十多樓時遇上強烈怪風。據網上片段所示，吊船左搖右擺，更被拋離至大廈外數十米遠，再兩次強撞玻璃幕牆，發出巨大聲響，玻璃幕牆碎裂剝落。

觀塘鴻圖道吊船故障 工人被困半空獲救

05月22日(五) 13:15

Tweet 分享



觀塘鴻圖道57號南洋廣場，今日(22日)12時39分，一組在上址大廈進行高空工作的吊船，懷疑發生故障，大廈外牆一面玻璃窗懷疑在意外中被撞爆，吊船上一名工人無奈被困半空，有途經市民察覺事件協助報警。消防員到場後展開救援，其後成功將吊船拉回天台位置，工人獲救並無受傷，意外原因有待調查。

Safety Alert:

- Suspended working platform (SWP) must be thoroughly inspected, examined and tested periodically in accordance with the statutory requirement;

- Every person working on the SWP shall receive proper training and possess a valid certificate of training;
- Wear suitable safety harness that is connected to a fall arresting system with independent lifeline, suitable anchorage or fittings on suspended working platform;
- Ensure SWP is installed with automatic safety devices which are capable of stopping or holding the load at the slope of working platform specified by the manufacturer; and
- Ensure SWP is of good mechanical construction, fitted with all necessary safety devices for the safe operation, and free from patent defect.



Refer to SHE Handbook for more information