

Work in Confined Space

Past Incident/ Accident:

【工業意外】屯門三工人清沙井垃圾 疑吸不明氣體 一人曾昏迷



中電地盤3工人亡 疑無安全設施

社會 07:00 2017/07/11 讚好 0

關注文章 儲存文章

分享: f

熱門 消委會 BNO 派錢1萬 反黑路人甲 自助餐優惠 兒童健康 烹飪教煮 劇情預告 超市大搜查



中電於紅磡一個鋪設地底電纜工程，昨發生奪命工業意外。3名外判工人在5米深地底狹窄密閉空間工作時，突然有洪水湧入，3人被困遇溺，救起搶救後證實無一生還。

保安員關水掣 墮沙井底喪命

星島日報 | 32.5k 人追蹤 追蹤

2015年8月12日 上午5:55



保安員出事的沙井口非常狹窄。

昔日東方 返回今日 電子報 即時新聞 東方新版意見箱

2013年6月9日 (日) 要聞港聞 兩岸國際 財經 娛樂 副刊 男極圈 體育 馬經

超毒沙井 數分鐘殺人

上一則 下一則

超毒沙井 數分鐘殺人

沙井隱形「殺手」，數分鐘奪一命。渠務署一名外判工人，昨凌晨與工友在中環路中一個沙井工作，他戴備氧氣罩及裝備深入三米深沙井內，期間與工友失去聯絡僅數分鐘，並迅速被發現暈倒井內及救出，惟送院搶救後，惜告不治。勞工處正調查事故及工人致死原因，初步並無可疑。有關關注勞工安全權益團體炮轟渠務署，事發後沒有清楚講述事件經過，罔顧一眾仍進行該類工作人員的安全，要求渠務署盡快作出交代，以免慘劇再現。



Safety Alert:

- Appoint a competent person to conduct risk assessment of confined space to identify all potential hazard before commencement of work;
- Implement a “Permit-to-work” system to ensure all necessary safety precaution are taken before certifying safe entry in writing such as arrangement of atmospheric testing, ventilation equipment and use of proper personal protective equipment;
- Any person who enters in the confined space must be properly trained with possession of valid certificate;
- Assigning a stand-by person to station at the entrance of confined space throughout the time of operation to maintain communication with the workers inside;
- Instruct stand-by person not to enter the confined space even in case of emergency, who should remain stationed outside and summon assistance of rescue team and public emergency services; and
- Formulate and implement proper emergency procedures, including provision of sufficient and suitable rescue equipment and presence of rescue team.



Picture source reference: Labour Department



Refer to SHE Handbook for more information