

Excavation Safety

Past Incident/ Accident:



新聞 一個月內第4宗奪命工傷

啟德地盤突地陷 工人墮坑亡

警方無收到相關報案

尖沙咀男工掘地期間電纜爆火花 頭髮燒焦手腳灼傷送院



挖泥機墮坑壓斃操作員

中年男工，昨晨在大埔操作挖掘機在村屋地盤施工，疑因泥土鬆軟致挖掘機翻側墮坑，工人未及跳車走避，慘遭挖掘機壓着不能動彈，工友睹狀欲救無從。消防把工人救出，送院搶救惜傷重不治。警方把事件列作工業意外，勞工處正調查意外原因，並向有關承建商發出「暫時停工通知書」停止使用挖掘機。



東方融資幫大忙
物業按揭無傍徨

申請熱線：
3600 2211

放債人牌照號碼：0552/2020

POWERED BY yahoo!

熱門:

- 升學顧問 減肥瘦身 海外升學
- 課程 幼兒課程 電話系統
- 市場推廣 婚紗攝影 網上商店
- 禮品 花籃 核數
- 商標 冷氣工程 英語
- 興趣班 不織布袋 五金廢料
- 會計 專業化妝 印刷
- 脫髮 宣傳方法

我的瀏覽記錄



更多新聞短片

東網電視

Safety Alert:

- Appoint a competent engineer to conduct risk assessment to identify all potential hazard associated with the work, taking into account the nature of work, the work environment, the sitting of plant and equipment and the ground condition;
- Examine every part of earth work, including the sitting of the equipment, to ensure that there is no sinkage of ground;
- Appoint an authorized party to conduct underground cable detection to mark location of underground utilities before digging;
- Fence off the operation zone of the machine as far as reasonably practicable with warning notice and adopting control measures to prevent any unauthorized entry into the area;
- Fence off the edge of excavated trench to prevent falling hazard;
- Appoint a competent person to conduct regular inspection of the excavated trench with completion of statutory inspection form;
- Take adequate measures to ensure operator does not operate machine on unstable surface;
- Ensure machine is only operated by a person who hold a valid certificate and is able to operate the machine safely by virtue of his experience and competence;
- Select a machine, as far as reasonably practicable, equipped with roll over protective structure/ tip-over protective structure and operator restraint system for operation on slopes; and
- Ensure the proper use of seat belt by the operator.



Refer to SHE Handbook for more information